Regina Flying Club

Airport

Regina Sask.

INSPECTION and REPAIR REPORT - May 21, 1949

AIRCRAFT:

AIRCRAFT:

ENGINE:

Piper Cub L4B Prospector, Serial No.235C. @F-EGI. Property of Prairie Flying Service, Regina, Sask.,

C of A - No. 2026

Expires February 14, 1949, Expires February 14, 1949,

C of R - No. 5818

Time since new: 360:50 Time since overhaul: No previous overhaul.

Type : Continental A-65-8F serial No. 5102168

Time since new: 360:50

Time since overhaul: No previous overhaul.

Time since top overhaul: No previous top overhaul.

PROPELLER:

Type: Lewis Serial No. 15763 Pitch: 45 Des. L 11CK.

P.C. No. -20

REASON FOR WORK: Renewal of C of A.

This aircraft has been weighed and center of gravity determined as per D.O.T. circular. 30 hour inspection and renewal of C of A inspection as follows:

Carried Out Completed Previously Not Applicable 46 - 36 - 1 49-14-1 44 - 6 - 2 44 - 6 - 144 - 6 - 3 47 - 50 - 6 48 - 46 - 1 46 - 37 - 147 - 40 - 2 49-14-3 47 - 50 - 347 - 50 - 5 A- PROPELLER

(1) Prop removed, hub and bolts inspected for cracks and corrosion, cleaned, primed and oiled.

(2) Prop boss, blades and sheathing inspected.

(3) Prop re-installed, bolts tensioned, locked and tracked.

B- ENGINE

30 hour inspection carried out. re-set, tested and re (1) Ignition System - plugs removed, cleaned, installed; wiring inspected for serviceability and condition, chaffing. Magnetos checked.