

NOTIFICATION OF THE MINISTRY OF INDUSTRY

No. 2 (B.E. 2513)

Issued under the Factories Act B.E. 2512

Re: Duties of Licensee to Operate Factory

By virtue of Section 39 of the Factories Act B.E. 2512, the Minister of Industry hereby prescribes rules and procedures which licensee to operate factory of whatever category or kind is under duty to comply with, as follows:

General Rules and Procedures

Chapter 1

Keeping of Factory and Machinery

Issued by virtue of Section 39 (1)

Article 1. Must provide regular inspection of the condition of factory building, and must maintain or repair the same so that they are secure and safe as the time the licence was granted.

Article 2. Must keep passage and working area clean, even, nonslippery and dry except the area where it may not be possible to do so.

Article 3. Must keep railings, stairs and floor or passage which are higher than the factory floor from 1.50 meters onwards in secure condition.

Article 4. Must store or arrange materials or other things in orderly manner so that they do not interfere with or obstruct passage or work and cause accidents.

Article 5. Must inspect and keep exits and emergency stairs in condition for immediate evacuation when there occurs an emergency.

Lieutenant General P. PUNAKIT
Minister of Industry.