

14
TOR:5008-D8-6

1 Montgomery Avenue, Toronto.
June 27th, 1946.

Mr. W. Le Sauvage,
Toronto Island Airport,
TORONTO, Ontario.

Dear Sir:

Receipt is acknowledged of your letter of
June 24th/46, regarding the accident to Piper Cub,
CF-DHF on Saturday June 22nd/46.

In order that the purpose for which re-
gulations relating to the reporting of accidents were
made may be more completely fulfilled, it is requested
that you forward this Department a report on the cause
of the accident in so far as you may be aware of it.

It has been reported that the carburettor
on these Continental Engines is sometimes apt to freeze
up. If this can be established by numerous reports, it
might be possible for this Department to take the ne-
cessary action to reduce the number of accidents from
this cause.

Yours truly,

ENTERED
IN ACCIDENT
RECORDS

67

DGJ/HT.
c.c. H.Q.

D.G. Joy,
District Inspector, Air Regulations,
Toronto.