

WINNIPEG FLYING CLUB

WINNIPEG, Man.

14
C O P Y
November 28, 1952.

District Superintendent,
Air Regulations,
Civil Aviation Division,
Department of Transport,
501 Power Building,
WINNIPEG, Manitoba.

Dear Sir:

In reply to your letter of November 19th, your file number 5008-D4-9, We wish to report an accident to one of the aircraft operated by this Club.

1. Canadian Aeronca 7DC, registration CF-DDI.
2. Owned by the Winnipeg Flying Club.
3. Pilot Mr. Lawrence George Stephenson, Private Pilot Licence No. WGP-2961.
4. The accident occurred at 15:15 hours on November 9, 1952.
5. The aircraft departed from Stevenson Airport, Winnipeg, and intended to return to the same airport without landing elsewhere.
6. The accident occurred one mile North of the town of Haddishville, Manitoba.
7. No injuries sustained.
8. Due to heavy landing, propellor and undercarriage fittings were damaged.
9. The aircraft was on an authorized flight by a member of this club.
10. Pilot decided to land when airspeed indicator became un-serviceable, and stalled about 20 feet off ground resulting in heavy landing.

Yours very truly,
THE WINNIPEG FLYING CLUB
H. TAYLOR (SGD.)
Manager.

Entered on
Accident
Cards