

Plate I.—Illustrating Mr. E. A. Sjostedt's Paper, "Notes on the Ores and Blast Furnace Plant of the Pictou Charcoal Iron Co. Ltd."




Plate II.—Illustrating Mr. E. A. Sjostedt's Paper, "Notes on the Ores and Blast Furnace Plant of the Pictou Charcoal Iron Co. Ltd."




Plate III.—Illustrating Mr. E. A. Sjostedt's Paper, "Notes on the Ores and Blast Furnace Plant of the Pictou Charcoal Iron Co. Ltd."




Plate III.—Illustrating Mr. E. A. Sjostedt's Paper, "Notes on the Ores and Blast Furnace Plant of the Pictou Charcoal Iron Co. Ltd."




Plate IV.—Illustrating Mr. E. A. Sjostedt's Paper, "Notes on the Ores and Blast Furnace Plant of the Pictou Charcoal Iron Co. Ltd."

