Statement of: Capt. A.R. Burnett, Officer Commanding, #63 L.A.D., R.C.C.C.

I inspected on 18/8/42 Vehicle No. CM-4202142, Ford, Station Wagon and found the following damages:-

1. Frame Bent,

2. Windshild Broken.

3. Radiator Grill Broken. 4. Radiator Smashed,

5. Fan Assembly Broken

6. Left Fender torn,

7. Hood bent.

8. Battery N/S

9. Steering Wheel bent.

also I found the front has been pushed in and Engine pushed back on frame with the front support smashed.

To the best of my ability I estimate the cost of the repairs will be £50/0/0

al. R. Burnett Cast