	DATE	TIME SUMMARY OF EVENTS
Camp Borden, Ont.	4-2-43	Harvard F.E. 467 turned up en its nose when pilet, R86794 LAC McKelvey, R., got his heel caught in rudder pedals en landing. After his heel was released he applied brake causing categorized Ol The pilet was uninjured.
		Yale 3450 turned up en nose when pilet attempted to turn to left en soft aerodreme at Categorised C2.  The pilet was uninjured.  The pilet was uninjured.  The pilet, R153689 LAC Tucker, M.C., was uninjured.
		Anson II 7240 went up en nose when taxiing en soft aerodrome en main aeredreme at appreximately 1630 heurs. The pilot, R98363 Flight Sergeant Everitt, R., Navigation Instructor, Were all uninjured. Categorized Co.
	5-2-43	Wemen's Division Basketball team played the Collegiate Girls team in Barrie and were very nicely entertained at the School afterward.  0800 hours C - 3000 feet, V - 10 miles. Selo. Flying washed in at 0815 hours, and washed out at 1400 hours due to soft runways. 53 hours sole. Flying time 338.35 hours.
		When Harvard 3175 swerved on landing it hit soft snow at side of runway at R.1 Edenvale and nosed up. The pilot, R113956 LAC Harvey, K. was uninjured. Categorized C2.
of charge		Harvard 2606 in a crosswind landing on icy runway at R.l Edenvale, slid sideways to snow at sides and nosed up at approximately 1027 hours. Pilet, R139343 LAC Harris, S.D. was un-
	6-2-43	0800 C.U. V - 10 miles. Hazy. Wind 140/10. Sele. Flying washed in 0800 hours, washed eut 1230 hours. 4 hours sole. Flying time 151.40 hours.
	7-2-43	0900 hours Ceiling 500 feet, visibility 1 mile. Flying washed but because of blissand
	3-2-43	0900 hours C.U. V- 10 miles. Wind 330/25. Dual. Flying washed in 0930, washed out 1100 hangars delayed action. Night flying 80 hours - 1900 hours to 0500 hours. Flying time

REFERENCE TO APPENDICES