

Father Point.

Lantern recovered, new flooring and repairs to house and painting. The work was performed by keeper with local assistance, at a cost \$126.10.

Green Island.

The buildings at this station are the oldest in the district and frequently require small repairs. During this season the cost of such repairs performed by keeper with local assistance, amounted to \$62.70.

Lower Traverse Light-ship.

A new deck was laid and repairs to hull and joiner work inside performed under supervision of Mr. P. Jobin and local assistance. Cost, \$1,288.89.

White Island Reef Light-ship.

Repairs to engine, boiler and fittings were performed by the engineer and assistant at the agency's forge. Cost, \$200.68.

Métis.

A new metal roof was put on the dwelling by the lowest tenderer Mr. J. R. Kane, roofer of Quebec, with other small repairs. Cost, \$156.07.

Orleans Range Light.

Two new masts with rigging to hoist dioptric lights were provided, the towers were levelled up and repairs to foundations required, owing to heaving of the soft soil were made by two workmen sent from Quebec. Cost, \$183.70.

Paspebiac.

The foundation of the tower required considerable repairs which were performed by the keeper and local assistants. Cost, \$58.

Pillars Lighthouse and Tower.

The dwelling-house which is old and in bad order is to be renewed. The repairs necessary to keep the station in working order, with repairs to boats allowed, were done by the keeper and local assistance at a cost of \$164.23.

Platon.

Repairs to tower and painting done by the keeper and assistance allowed. Cost \$15.

Pointe des Monts.

Repairs, clapboarding tower and general repairs to windows, floors, doors, roof, masonry and painting. Two men were sent from Quebec, who with local assistance did the work, under the supervision of Mr. Pierre Jobin, at a cost of \$187.20.