

INDEX.—Continued.

	PAGE.		PAGE.
Chain Tongs.....	77	Hook Plates.....	58
Chain.....	108	Hose, Rubber.....	96
Chucks, Lathe.....	65-68	“ Linen.....	96
“ Planer.....	67	“ Couplings.....	51
“ Drill.....	69	“ Branches.....	51
“ Valve.....	6	“ Clamps.....	51
“ Drill Holder.....	81	“ Benders, etc.....	51
Circular Saws.....	89	Inspirators.....	72-74
Cylinder Lubricators.....	54	Injectors.....	72-74
Die Stocks.....	34	I. X. L. Pipe Machine.....	8
Dies.....	34-46	Iron Pipe.....	50
Die Plates.....	35	Iron Planers.....	2
Door Clamp.....	13	“ Cocks.....	53
Dovetailing Machine.....	12	Jack Screws.....	76
Drag Saws.....	90	Key Seat Slotters.....	5
Drills (Twist).....	47-50	Knife Grinders.....	70
“ (Ratchet).....	65	Knives (Planer).....	98
Drill Holders.....	81	“ (Moulding).....	98
Drilling Machines.....	47-9	Lathes, Engine.....	3-7
Drive Chain.....	60-61	“ Gap.....	4
“ Wheels.....	62	“ Turret.....	4
Drop Hammers.....	5	“ Bench.....	6
Eclipse Saw Mills.....	14	“ Brass.....	6
Explosive Band.....	14	“ Fox.....	6
Edgers.....	15	“ Gauge Wood.....	12
Elevator Buckets.....	94	“ Spoke.....	12
Emery Machinery.....	70	“ Wood.....	11
“ Wheels.....	71	“ Foot.....	7
Engines (Stationary).....	19	Lathe Dogs.....	79-81
“ (Automatic).....	20	Lath Yarn.....	16
“ (Marine).....	20	“ Bolter.....	16
“ (Portable).....	20	“ Machine.....	16
“ (Upright).....	22	“ Equalizer.....	16
“ (Hoisting).....	24	Lane Mills.....	14
“ (Gas).....	26	Lubricators.....	54
Engine Lathes.....	3	Machine Bolts.....	105
Ewart's Drive Chain.....	60-61	Machine Knives.....	97
Expansion Joints.....	51	Malleable Fittings.....	54-57
Fans.....	28-31	Matcher Heads (Shimer).....	97
Files and Rasps.....	63-64	Marine Engines.....	20
Force Pumps.....	87	Mill Dogs.....	15
Forges (Portable).....	75	Milling Machines.....	4
Forge Furnace.....	5	“ (Valves).....	6
Gauge Cocks.....	52	Mitre Machine.....	12-113
Governors.....	32	Mortising Machine.....	13
Grindstones.....	108	“ (Hub).....	13
Guy Wire.....	108	Moulding.....	11
Hammers (Bradley).....	5	“ Knives.....	98
“ (Drop).....	5	“ Patterns.....	98
Handle, Saw.....	12	McClosky Separators.....	13
Hangers.....	108	Nuts.....	107
Hoisting Engines.....	24	Oil Cups.....	62
Hoists, Harrington.....	86	Ore Crushers.....	70
Hoop Machinery.....	33	Packers.....	16

r.

quick and
as—light,

r lb.

“

“

gal.

“

d irregu-
with the

PAGE.

72-74

108

108

5-9

5

9

16

105

106

7-13

16

90

90

5

58

25

15

15

103

106

108

58

5