TABLE OF CONTENTS.

INTROI	DUCTION: Wet and Dry Processes of	Cop	per	Extr	action		. 5
Th	e Hunt and Douglas Process; Workin	σ Di	rect	ions			6
I.	Grinding the Ore	8			•	•	0
н.	Calcining the Own	•	•	•	•	•	7
III.	Dissolving the Copper	•	•	•	•	•	8
IV.	Precivitation de Copper	•	•	•	•	•	12
V.	- confidenting the Copper .	•	•				17
	Melting and refining the Copper	•	•				18
VI.	Arrangement of the Plant	•	•	•		•	19
Append	1X.						
I.	Assaying for Copper and for Iron						
П.	Preparation and use of Iron Sponge	•	•	•	•	•	20
III.	Use of Tin Plate Scrap	•	•	•	•	•	24
IV.	Chemistry of the Hunt and Douglas I	•	•	•	•	•	27
V.	Patent Specification	roce	SS	•	•		28
VI.	Patent Specification	•	•	•	•		33
VII.	What Ores may be treated by the Pro	eess		•	•		34
	Practical Working of the Process .		•				35
VIII.	The Treatment of Silver and Gold On	res ,	,				37