

*The maintenance of the temperature of a curing room at 60° at all times, even with a high outside temperature is therefore a problem an economical solution whereof is more difficult to find than is imagined at first sight and which necessarily calls for rather costly improvements which are however compensated for by the benefits to be derived.*

For all additional information, apply to the Department of Agriculture, Quebec.

Quebec, 12th March, 1898.

GABRIEL HENRY, B. Sc., M. CAN. Soc. C. E.