

Thermomètres

COMPARAISON DE L'ÉCHELLE FARENHEIT, RÉAUMUR ET CENTIGRADE.

Zéro Farenheit correspond à 18 (près) Centigrade et 14.4 Réaumur au-dessous de Zéro (1).

CENT.	FAH'T.	RMR.	CENT.	FAH'T.	RMR.	CENT.	FAH'T.	RMR.
100	212	80	55	131	44	10	50	8
99	210.2	79.2	54	129.2	43.2	9	48.2	7.2
98	208.4	78.4	53	127.4	42.4	8	46.4	6.4
97	206.6	77.6	52	125.6	41.6	7	44.6	5.6
96	204.8	76.8	51	123.8	40.8	6	42.8	4.8
95	203	76	50	122	40	5	41	4
94	201.2	75.2	49	120.2	39.2	4	39.2	3.2
93	199.4	74.4	48	118.4	38.4	3	37.4	2.4
92	197.6	73.6	47	116.6	37.6	2	35.6	1.6
91	195.8	72.8	46	114.8	36.8	1	33.8	0.8
90	194	72	45	113	36	Zero	32	Zero
89	192.2	71.2	44	111.2	35.2	1	30.2	0.8
88	190.4	70.4	43	109.4	34.4	2	28.4	1.6
87	188.6	69.6	42	107.6	33.6	3	26.6	2.4
86	186.8	68.8	41	105.8	32.8	4	24.8	3.2
85	185	68	40	104	32	5	23	4
84	183.2	67.2	39	102.2	31.2	6	21.2	4.8
83	181.4	66.4	38	100.4	30.4	7	19.4	5.6
82	179.6	65.6	37	98.6	29.6	8	17.6	6.4
81	177.8	64.8	36	96.8	28.8	9	15.8	7.2
80	176	64	35	95	28	10	14	8
79	174.2	63.2	34	93.2	27.2	11	12.2	8.8
78	172.4	62.4	33	91.4	26.4	12	10.4	9.6
77	170.6	61.6	32	89.6	25.6	13	8.6	10.4
76	168.8	60.8	31	87.8	24.8	14	6.8	11.2
75	167	60	30	86	24	15	5	12
74	165.2	59.2	29	84.2	23.2	16	3.2	12.8
73	163.4	58.4	28	82.4	22.4	17	1.4	13.6
72	161.6	57.6	27	80.6	21.6	18	—	14.4
71	159.8	56.8	26	78.8	20.8	19	2.2	15.2
70	158	56	25	77	20	20	4	16
69	156.2	55.2	24	75.2	19.2	21	5.8	16.8
68	154.4	54.4	23	73.4	18.4	22	7.6	17.6
67	152.6	53.6	22	71.6	17.6	23	9.4	18.4
66	150.8	52.8	21	69.8	16.8	24	11.2	19.2
65	149	52	20	68	16	25	13	20
64	147.2	51.2	19	66.2	15.2	26	14.8	20.8
63	145.4	50.4	18	64.4	14.4	27	16.6	21.6
62	143.6	49.6	17	62.6	13.6	28	18.4	22.4
61	141.8	48.8	16	60.8	12.8	29	20.2	23.2
60	140	48	15	59	12	30	22	24
59	138.2	47.2	14	57.2	11.2	31	23.8	24.8
58	136.4	46.4	13	55.4	10.4	32	25.6	25.6
57	134.6	45.6	12	53.6	9.6	33	27.4	26.4
56	132.8	44.8	11	51.8	8.6	34	29.2	27.2

(1) Lorsque le thermomètre Farenheit marque 32 au-dessus de zéro, le Centigrade et le Réaumur indiquent 0, c'est-à-dire "température glace-fondante." 13 degrés Farenheit au-dessous le zéro correspondent à 25 Centigrade et 20 Réaumur également au-dessous de zéro.