

INDEX TO PROCEEDINGS

	Page
Synopsis of First Convention, Winnipeg 1913	7-10
Report of Second Convention, Edmonton 1914	11-94
Auditors' Report	16
Brass Pipe and Fittings, Standardization of	76, 77, 81-86
Bar Fixtures and Drinking Fountains	76, 80
Cast Iron Pipe and Fittings, Standardization of	46-56, 68-70
Cleanouts	74, 76, 92
Constitution and By-laws, Alteration to	15, 18
Examination of Plumbers, Resolution on	86-91
Fixture and Floor Drain Traps	76
Floor Drains from Lavatories and Kitchens	74-76
Garage Drains	73, 74, 80
Greetings from Kindred Associations	16
Legislative Committee and Duties of	91
Meeting Place of Next Convention	56-58
Members, list of	95-96
Name for New Standard Pipe and Fittings	77
Office bearers for 1914-1915	58, 59
Paper by E. P. Fletcher, on "Explosions in Sewers and Conduits"	92-94
Pipe Terminals	23-45
Plumbing Inspectors Department, Resolution on	92
President's Address	13-14
Proceedings to be Printed	94
Rain Water Leaders	71-73
Research Committee's Report	60-68
Research Committee to have samples made, etc.	92
Soil, Waste and Vent Pipes, Sizes of	18-23, 45, 46, 77-79
Technical Education, Resolution on	91-92
Voting Power of Delegates	15, 18

Photos and Illustrations

Officers of C. I. S. E. 1913-1914	6
Group of Delegates attending Winnipeg Convention 1913	10
Pipe Terminal, Recommended by Saskatoon Committee	24
Pipe Terminal decided upon by Convention	48
Charts showing Frost Closure of Pipe Terminals	27, 31, 33
Photos showing Frost Closure of Pipe Terminals	29, 30, 35, 36
Tables and Drawings on Standardization of Cast Iron Pipe	48-52
Defective Brass Globe Trap, discovered by Smoke Test	63
Section of Defective Lead Clean Sweep Trap, discovered by Smoke Test	64
Defective Syphon-let Closet Bowls, discovered by Smoke Test	64
Brass Globe Trap, with all its parts intact	64
Garage Floor Drains	73