

## APPENDIX

## RETURN of the Illuminating Power and Purity of Gas

INSPECTION OFFICE.	Illuminating Power.						Sulphur per		
	Highest.	Lowest.	Average.	Standard.	No. of times below Standard.	No. of Tests.	Highest	Lowest.	Average
	Candles.	Candles.	Candles.	Candles.			Grains.	Grains.	Grains.
Quebec :—									
July.....			17 05	16	0	1	31 93	27 98	29 95
August.....			17 17	16	0	1	33 58	28 16	30 87
September.....			17 45	16	0	1	29 09	27 25	28 75
October.....			16 09	16	0	1	33 46	32 71	32 73
November.....			16 63	16	0	1	36 87	35 21	36 04
December.....			16 77	16	0	1	33 36	28 25	30 80
January.....			16 29	16	0	1	25 40	23 39	24 39
February.....			16 43	16	0	1	22 92	20 49	21 70
March.....			16 20	16	0	1	25 78	16 50	21 14
April.....			16 65	16	0	1	21 03	12 04	16 53
May.....			16 49	16	0	1	17 53	14 00	15 76
June.....			16 38	16	0	1	19 79	16 98	18 38
					0	12			
Sherbrooke :—									
July.....			26 42	16	0	1			
August.....			27 55	16	0	1			
September.....			28 55	16	0	1			
October.....			28 44	16	0	1			
November.....			29 17	16	0	1			
December.....			27 27	16	0	1			
January.....			30 00	16	0	1			
February.....			23 97	16	0	1			
March.....			28 58	16	0	1			
April.....			27 36	16	0	1			
May.....			27 74	16	0	1			
June.....			25 80	16	0	1			
					0	12			
Chatham :—									
July.....	16 39	16 03	16 18	16	0	3			
August.....	16 50	16 22	16 39	16	0	3			
September.....	16 40	16 05	16 26	16	0	3			
October.....	16 50	16 21	16 35	16	0	3			
November.....	16 53	16 31	16 40	16	0	3			
December.....	16 77	16 40	16 58	16	0	3			
January.....	16 34	15 64	15 99	16	1	3			
February.....	16 36	16 04	16 19	16	0	3			
March.....	16 47	16 21	16 32	16	0	3			
April.....	16 39	16 09	16 21	16	0	3			
May.....	16 39	16 13	16 27	16	0	3			
June.....	16 53	16 36	16 44	16	0	3			
					1	36			