




*Bower Furnace for Coating Iron and Steel.—Fig.4.—Horizontal Section through Muffle, shown by L P in Fig. 2.*

THE BOWER FURNACE.




FIG. 1.—THE MESSINGER BOILER FEEDER.




FIG. 2.—MESSINGER BOILER FEEDER AND ATTACHMENTS.