

FRC/AO'D

3334  
Ottawa, Ontario, October 17, 1949.

5008-B18-16

Engine Overhaul Periods - Extension  
Tantramar Air Services

5008-B18-16 <  
5258-290 (CAE)

District Controller of Air Services,  
P.O. Box 42,  
Moncton, New Brunswick.

Attention: District Aircraft Inspector

1. Reference is made to your letter dated the 6th instant relative to the request of the subject company for an extension of 50 hours over and above the basic period for Continental A65-8 engine installed in Piper J3 - CF-BRP.
2. In accordance with the content of paragraph 3 of Information Circular T/8/48 you are at liberty to grant approval of 50 hours temporary authority for this engine provided you are satisfied that the conditions outlined in this paragraph prevail.

*HRS*  
for (H.S. Rees),  
Chief Aeronautical Engineer.

*P*