

PLACE	DATE	TIME	SUMMARY OF EVENTS - Page 12 -	REFERENCE TO APPENDICES														
	29-4-44		<p>Edenvale: Flying washed in 0800 hours, washed out 1730 hours. Flying time 65.55 hours.</p> <p>At 0950 hours Harvard II 2769 groundlooped on Main Aerodrome. The pilot, R219204 LAC Pscheidt, K. was not injured. Categorized D.5.</p> <p>A picture was shown in the Station Theatre at 1945 hours.</p>															
	30-4-44		<p>0900 hours ceiling average, visibility unlimited. Flying washed in at 1300 hours, washed out 1800 hours. Flying time 250.55 hours. No night flying.</p> <p>Total flying hours for the month: 9527.50.</p> <p>Edenvale: Flying washed in 1300 hours, washed out 1800 hours. Flying time 43.55 hours.</p> <p>Padres conducted Communion services at 0800 hours and the regular services at 1100 hours.</p> <p>Two pictures were shown in the Station Theatre, one at 1800 hours, and the other at 2000 hours.</p> <p>Aircraft Strength as at 2359 hours:</p> <table data-bbox="1404 838 1625 953"> <tr><td>Harvard II</td><td>62</td></tr> <tr><td>Harvard II B</td><td>31</td></tr> <tr><td>Ansons</td><td>8</td></tr> <tr><td>TOTAL</td><td>101</td></tr> </table> <p>Unserviceable:</p> <table data-bbox="1404 983 1625 1072"> <tr><td>Harvard II</td><td>4</td></tr> <tr><td>Harvard II B</td><td>3</td></tr> <tr><td>TOTAL</td><td>7</td></tr> </table>	Harvard II	62	Harvard II B	31	Ansons	8	TOTAL	101	Harvard II	4	Harvard II B	3	TOTAL	7	
Harvard II	62																	
Harvard II B	31																	
Ansons	8																	
TOTAL	101																	
Harvard II	4																	
Harvard II B	3																	
TOTAL	7																	