

---

The back, east and west ends stand much in need of pointing, and it would be desirable to have it done before the cold weather sets in, as the mortar adheres better in warm weather.

All the Stations mentioned in my last Report as requiring boats have been furnished with them.

I have the honor to be, Sir,  
Your obedient servant,

(Signed) J. MITCHELL,  
*Superintendent of Lights.*

J. H. HARDING, Esq., Agent,  
Department of Marine and Fisheries,  
St. John, N.B.