June 7.—	To paid working at Mayflower, £ Working at cars, Making breaks for cars,		12 12 3	9 6 0	1 <u>č</u>	8	3			,
14.	Working at Mayflower,	11	11	3	10	U		•	*	
12.	Working at cars,	ī	7	6		-				
	Making breaks for cars,	$ar{2}$		Ŏ						
	Ward, making patterns,	1	2	6		ŀ				
	Making steps for 2nd class cars,	0	6	0						
	,				16	7	3			
21.	Working at Mayflower,	1	16	3				*		
	Working at Sir Gaspard,	8	0	$7\frac{1}{2}$						
	Cleaning car wheels,	0	5	0				fo.		
	Taking wheels to Wier's wharf,	0	16	6					,	
	Making hooks for cars,	0	18	. 0						
				<u> </u>	11	16	$4\frac{1}{2}$			
20.	Making square and straight	- 4								
	edges,	0	15	0				,		
	Working at cars,	1	2	6						
28.	Working at Sir Gaspard,		11	3						
	Working at Joseph Howe,		11	3	2					
	Work at cars,	0	11	3						
•						1,1	3			•
	Lane, trucking 200 feet pine,				0	2	6	~ ^	~	
					,			53	5	$7\frac{1}{2}$
July 5.	-To paid working at platform cars,	1	17	6	,					•
ouly o.	Working at engine Sir Garspard,		1 5	ŏ					,	
12.	Engine Sir Gaspard, and mak-	_		•						
	ing house for do.	1	2	6						
	Engine Sir Gaspard, omitted	_	_	_	•					
	last week,	1	0	0						
*	Engine Joseph Howe,	1	0	0						
	Passenger cars,	0	7	6	•					
•	Engine Mayflower,	· 0	6	0			1 14	•		7
	Making hooks for platform cars,	0	18	0		¥	•			
					8	6	6	•		
19.	Working at engine J. Howe,	0	10	0						,
•	Ditto Sir Gaspard,	2	10	. 0		•				
	Making house for do.	1	10	0	•					
	Working at cars,	2	0	0						
	Making rings and staples for				•					
	horse car,	0	12	0						
	•				7	2	0		,	
26.	Working at engine Sir Gaspard,		10	0						
	Ditto Joseph Howe,	3	1	0	18		•			
•	Shifting platform car wheels,	0	17	6						
	Making hooks for cars,	0	6	0						
-	Screwing bolts for platform cars,	0	7	6						•
·	Making house for engine Sir	_		_	•					
	Gaspard,	0	17	6						
-	Working at cars,	3	0	0						
	Cleaning carriage wheels,	0	9	.3	·					,
	Making house on eng. J. Howe,	0	17	6			0	G =	٠.	_
	 3				10	6	3	25	14	9
-	•		t							