

20/10/1927.

October 10, 1927.

Dear Sir:- Ho-Stone-Childs Joint Irrigation
System - Indian Division House.

It is understood that the Indian intention on the above mentioned irrigation system are out of order and require some repairs at an early date. Mr. Hill is instructing Engineer Warren to make the necessary repairs to the Indian division house, but has no money on hand with which to pay for any material.

Engineer Warren is being instructed to purchase any material necessary for these repairs and submit the accounts to your office in order that you may forward the same on to Ottawa for payment. You will, therefore, act accordingly.

WHD/ED.

Yours truly,

H. H. Ditchburn,
Indian Commissioner for B. C.

H. MacLeod, Esq.,
Indian Agent,
Okanagan, B. C.