## CONTENTS

Miscellaneous Illustrations Description of Balloon Framing Sections of Bay Window Frames Turned Mouldings and Carved Newels Shingling, Different Methods Shingling Hip Rafters	171 172 173 174 174 175
Illustrations of Shingling. Flashings for Valleys.	175 176 177
PART IV	
USEFUL TABLES AND MEMORANDA FOR BUILDERS	
Lumber Measurement Table.  Strength of Materials.  Table of Superficial or Flat Measure.  Round and Equal-sided Timber Measure.  Shingling.  Table for Estimating Shingles.  Siding, Flooring and Laths.  Excavations.  Number of Nails Required in Carpentry Work.  Sizes of Boxes for Different Measures.  Masonry.  Brick Work.  Slating.  To Compute the Number of Slates of Compute the N	182 183 183 183 184 184 184 185 185 185 185 185 185 185 185 185 185
Required per Square	39 39 39 30 31 31 31 32 22 33