



A mile of trees "shorn" to allow of the passage of wires. As thousands of stubs have been left, nearly every tree will die. In winter the effect of "shearing" is horrible. Co-operation will largely prevent such mutilation in the future.



Trees dehorned (headed back) to allow of the passage of wires. So mutilated they will die. Observe the stubs!