THIS FORM IS TO BE USED IN ACCORDANCE WITH PARAGRAPHS 1931 AND 1932, K.R. & O. FOR THE R.C.A.F. AND AIR FORCE ADMINISTRATIVE ORDER A,39/1.

## DAILY DIARY

-1-

OF

NO. I S.F.T.S. (UNIT OR FORMATION) Camp Borden, Ontario.

TIME	SUMMARY OF EVENTS	DEFENSAL .
	The first is the time of the second was a second to the second of the se	REFERENCE TO APPENDICES
	STRENGTH	
	R.C.A.F. Officers (Staff) 82	
	R.C.A.F. Airmen (Staff) 727.	6
	R.A.F. Officers Army Officers (Staff) C.D.C. 2	
P P	Army O.R.'s (Staff) C.D.C. 4/ Army O.R.'s (Staff) O.P.C. 2/	
	Civilians 133 .	
	TOTAL 1263	
	NIL William Francis in Color of State o	
	Tale 3388 spun around and nosed over damaging propellor and crank shaft. Accident was	
	caused by wheel of aircraft slipping against checks while the engine was being run up.	
3		
	Accident took place at 1330 at the main aerodrome and categorized as C.h.	
		1
	during night flying operations. The pilot Aus. h117h2, LAC. Comphell F.C.	
	The cause was attributed to the pilots lack of experience. Coferent and de Co	
一年 一日		Caused by wheel of aircraft slipping against checks while the engine was being run up.  No. R891h7, LAC, Stewart, L.W., Aero- Engine Mechanic B was authorized to run up engine.  Accident took place at 1330 at the main aerodrome and categorized as C.h.  Harvard 3169 collided with another aircraft at taxi post at main aerodrome at 21,35 hrs.  during night flying operations. The pilot Aus. h117h2, LAC, Campbell, K.G. was uninjured.  The cause was attributed to the pilots lack of experience. Categorized as C.l.