

APPENDIX

RETURN of the Illuminating Power and Purity of Gas

INSPECTION OFFICE.	Illuminating Power.						Sulphur per		
	Highest.	Lowest.	Average.	Standard.	No. of times below Standard.	No. of Tests.	Highest	Lowest.	Average
	Candles.	Candles.	Candles.	Candles.			Grains.	Grains.	Grains.
Windsor—									
July.....			18·00	16	0	1			
August.....			16·86	16	0	1			
September.....			17·56	16	0	1			
October.....			17·00	16	0	1			
November.....			18·00	16	0	1			
December.....			16·86	16	0	1			
January.....			17·21	16	0	1			
February.....			16·86	16	0	1			
March.....			17·00	16	0	1			
April.....			16·50	16	0	1			
May.....			16·00	16	0	1			
June.....			16·70	16	0	1			
					0	12			
Woodstock—									
July.....			20·00	16	0	1			
August.....			20·00	16	0	1			
September.....			19·22	16	0	1			
October.....			19·58	16	0	1			
November.....			24·00	16	0	1			
December.....			23·24	16	0	1			
January.....			24·24	16	0	1			
February.....			22·00	16	0	1			
March.....			20·20	16	0	1			
April.....			19·74	16	0	1			
May.....			23·10	16	0	1			
June.....			20·40	16	0	1			
					0	12			
Montreal—									
July.....	18·53	16·92	17·84	16	0	9	32·04	31·85	31·94
August.....	19·60	17·46	18·46	16	0	9	24·57	12·78	18·67
September.....	22·08	17·50	18·73	16	0	9	20·26	13·71	16·98
October.....	20·95	18·12	19·00	16	0	6	30·60	24·06	27·33
November.....	19·63	17·17	18·65	16	0	9	28·10	24·70	26·40
December.....	19·97	17·51	18·79	16	0	8	26·64	22·94	23·94
January.....	19·77	17·83	18·94	16	0	9	21·70	20·22	20·96
February.....	20·16	17·71	18·85	16	0	8	24·57	18·09	21·33
March.....	24·71	18·01	20·22	16	0	10	22·64	22·18	22·41
April.....	25·18	19·34	21·80	16	0	8	19·29	16·08	17·68
May.....	28·99	21·27	23·85	16	0	10	13·36	11·81	12·58
June.....	26·36	22·20	23·57	16	0	8	18·79	10·01	14·40
					0	103			