

The declared quantities were verified on the basis of numerous business papers and documents which the inspectors were allowed to read. Among them were:

- computer print-outs and receipts relating to the origin and use of the purchased feedstock (name of supplier covered),
- computer lists of the sold quantities of the substance and the receiving countries (names of customers covered),
- storage papers,
- weight cards and
- quantity figures contained in the facility diary (parameters of the procedure covered).

Verification also extended to the quantity and yield of the individual batches.

The declared stockpile of pure substance was verified by on-site inspection.

All documents and receipts concerning quantities were taken under lock and key in the facility; they are available to the "inspectorate".

## 2.2 Results

2.2.1 The results of the trial inspection were recorded in the agreed short report form.