

4 MONTH TESTS:

Remarks concerning exposed specimens.

All these were of natural elements. They were brought in and kept 2 or 3 months before testing, and allowed to warm so as to survive on the first, and insure a test not being made on a frozen specimen. There were no external signs of any effect produced by 4 months exposure.

All these were of Portland cement. They were, when necessary, brought into the laboratory and kept there for 2 or 3 hours before being tested, so as to insure that no tests were made on frozen briquettes.