




FIG. 1.

INSTRUMENTS CONSTANT

The parallel plate screw instrument mentioned previously (an advantage in cold weather—bronzed with platinum—lacquer to preserve the surface, and like all the others supplied with an adjustment).
 Engineers' Transit, (in the form of a level to telescope).
 Engineers' Transit, Fig. 1.

Box Sextant without telescope.
 do. with telescope.
 do. artificial horizon.

Transits or Theodolites, for use by competent workmen, and usually on hand, for sale.

COMPASSES

6 inch best vernier compass, complete

5 do.

6 inch plain do.

5 do.

4 do.

Railroad Compass, 5 inch

Sights made to fold

2½ inch Surveyors' Compass

to.....

do: do.

Prismatic Compass, 2½

\$15 to.....

Binnacle Compasses with

to

Pocket Compass in magnetic

do. magnetic

do. brass

do. watch