## R.C.A.F. R. 65 20M-5-41 (186) H.Q. 1062-3-50

THIS FORM IS TO BE USED IN ACCORDANCE WITH PARAGRAPHS 1931 AND 1932, K.R. & O. FOR THE R.C.A.F. AND AIR FORCE ADMINIS-TRATIVE ORDER A.39/1.

## DAILY DIARY

## (UNIT OR FORMATION) No. 1 S.F.T.S., Camp Borden, Ontario.

| PLACE             | DATE     | TIME | SUMMARY OF EVENTS  | REFERENCE  |
|-------------------|----------|------|--|------------|
| Camp Borden, Ont. | 26-10-42 |      |  | APPENDICES |
|                   |          | •    | At 0800 hours ceiling 6000 feet visibility 10-12 miles, scattered clouds at 2500 feet,<br>wind-W.N.W. 15-20 miles per hour, bad cross winds all day. Washed in at 0800 hours and<br>washed out at 1800 hours, $5\frac{1}{2}$ hours dual and $4\frac{1}{2}$ hours solo. Night flying 1900 hours to<br>0230 hours, wind 28-30 miles per hour.<br>Total flying time 448.25 hours. |            |
|                   |          |      | Harvard 2938 piloted by G.B.1318581 LAC Chun, H.J., second pilot R137436 LAC Tyrrell, W.A.,<br>force landed two miles east of Cookstown, Ont., at 1445 hours. Occupants uninjured. While mutual<br>instrument flying, engine started to miss and did not pick up. Force landed and struck f ence.  | 1.         |
|                   | 27-10-42 |      | At 0800 hours ceiling 5000 feet visibility 6 miles with snow moving in from Southwest. Wind-<br>Southwest, 15-20 miles per hour. 0815 snow, ceiling zero visibility zero. Heavy Local snow<br>in the afternoon. Flying washed out.<br>Total flying time 24.45 hours.   | 9          |
|                   | 28-10-42 |      | At 0800 hours visibility 10-15 miles ceiling unlimited. Wind-Southwest, 6 to 10 miles per<br>hour. 10 hours solo, washed in at 0800 hours and washed out at 1800 hours. Night flying<br>1900 hours to 0345 hours.<br>Total flying time 560.15 hours.   |            |
|                   |          |      | Harvard II 3217, pilot P/O C.H. Reeves (J13095), pupil R152656 LAC Campbell, J.W. nosed<br>up on main aerodrome after landing at 1745 hours. Occupants uninjured. Application of brakes<br>to avoid collision raised tail which wind raised, causing nose up. Categorized #C".   |            |
|                   | -        |      | Harvard II 3084 piloted by F/O T.W. Handforth (J8376), pupil G.B.1314759 LAC Benfield, W.P.,<br>dropped on starboard wing on landing at Edenvale at 2000 hours. Student levelled off too<br>high and stalled aircraft. Occupants uninjured. Categorized "C".   | 53.        |

Page 9

SECRET