

		G	§
Gates, blowing in			60
Grove's cell, military pattern, data			page 82
" " " making up			82
Galvanometers			168-190
" astatic			171
" ballistic			181
" differential			182, 183
" " Latimer Clark's pattern			183
" effect of an instantaneous current on			179, 180
" figure of merit			188
" limits of deflection to obtain good readings			185-187
" measuring resistance of			204
" precautions to be taken to prevent injury to			184
" sine			172
" shunts			176-178
" tangent			173
" Thompson's reflecting			174-175
" " " setting up the instrument			175
" three-coil			170
Glue, marine			page 83
Guncotton			13-16
" application			16
" charges, precautions when making up			page 62
" compressed			13
" detonators			31, 33, 35, 37, 41, 42
" " dimensions of			pages 70 and 71
" " electrical			page 71
" " testing			113, 116-118
" dimensions and weights of various sizes			page 65
" dry, storage of			29
" drying of wet guncotton			15
" granulated			13
" magazines			28
" makeshift detonators for			35, 41
" packing cases for			28
" precautions when using			page 59
" primer preparation of			48, 49
" " indiarubber bags for			49
" " precautions when making up			page 61
" price of			page 66
" storing			15
" test to ascertain dryness			15 (6)
" testing			111
" time required to dry			page 65
" various shapes			13 page 65
" wet, detonation of			14
Gunpowder application			12
" charges, precautions when making up			page 61
" " bags for			52
" fuzes			31, 32, 37, 39, 42
" magazines			25-27
" makeshift fuze			39
" precautions when using			page 59
" preparation of primer			47
" price of			page 65
" primers, precautions when making up			page 61
" size of grain			page 65
" " suited to Military Engineering Land operations			11
" testing			110
" volume occupied by			page 65
		H	
Hasty demolitions			68