CANADIAN AGRICULTURAL MACHINERY. Plate: 4.

Knotting Mechanisms.

Fig. 11. Massey-Harris.





Fig. 12. Frost and Wood.



Fig. 13. Frost and Wood.



Mechanical Engineers 1901.

Fig. 14. Maxwell.

