Statement Showing the Number and Condition of Car Stock, &c., on December 31st, 1879.—Continued

DESCRIPTION.	1879.	REMARKS.
Grain Cars Dump Cars Snow Ploughs	44 52 2	In good order (flat cars) fitted with hoppers. In good working order. In good order, the winged plough has had new frame and housing, and the flanger plough refitted and repaired.
the spectrum states and states and states and	-	" North-western " Division.
Passenger Cars Second Class Emigrant Cars Baggage and Smoking Baggage, Express and Mail Baggage Cars Excursion Cars Auxiliary Cars Box Cars Snow Ploughs	7 2 2 4 1 4 1 39 30 101	Two have been thoroughly overhauled and painted, the others are in fair running order. In fair running order. In fair running order. Two have been thoroughly overhauled and re-painted ; the others are in fair running order. In fair running order. These are fitted in summer with seats, and light frame housing for passenger traffic. In winter these fittings are taken off, and the cars used as flats ; they are in good order. In good order ; equipped with appliances and tools, ready for immediate use. In good order ; two have been built in Company's works this year. In good order : In good In good In good In good In good In good In go

P. CLARKE, Mech. Superintendent.

32

....