



The schematic map gives some indication of slum distribution in Saint John. The bounded areas in the West Side and the North End represent sub standard housing districts. Of the 976 buildings in these areas, by a triple cross-reference analysis, 595 of them are rated as fair or poor structurally, 726 of them are rated as fair or poor with respect to their material condition, and 822 of them are rated as fair or poor by standards of maintenance. The enlarged portion of the map accomodates part of the most severe sections. Each dot or square represents the approximate location of a substandard structure. The dots indicate buildings needing remedial treatment; the squares indicate buildings requiring probable demolition. The wavy line leaving the circle indicates the direction of the photograph on the opposite page, with the new harbour bridge under construction in the background.