

2. Composition of the inspection team

The inspection team consisted of:

- an analytical chemist (Ph.D.), research officer at the Swedish Defence Research Establishment;
- a chemical process engineer (D.Eng.Sci.), research officer at a technical university;
- a factory inspector (M.E.), deputy chief of the local division of the Swedish Labour Inspectorate.

3. Inspection equipment

Inspection equipment was furnished by the facility.

4. Activities prior to the arrival of the inspection team on-site

The facility was notified of the exact inspection date one month in advance.

5. Advance preparations on-site

A controller group arranged accommodation for inspectors in a nearby city. No physical preparations on-site were undertaken. The facility designated points of contact and informed relevant personnel.

6. Escort and points of contact arrangements

Only escorts from the facility were provided. Points of contact were specified in the "facility attachment"; the inspectors met these points of contact during the initial visit.

7. Other participants

The NTI was managed by a controller group from the Swedish Defence Research Establishment. A limited number of representatives from concerned governmental agencies took part in the NTI as observers.

8. Duration of inspection and initial visit respectively

- Initial visit: 2.5 days
- Preparation of "facility attachment": 10 days
- Inspection (actual visit): 1 day
- Inspection (report preparation): 1 day.