

REPAIRS TO AIRCRAFT OR REMARKS	AIR ENGINEER'S SIGNATURE CERTIFYING AIRCRAFT AIRWORTHY	PILOT'S COUNTERSIGNATURE ACKNOWLEDGING AIRCRAFT AIRWORTHY AND CERTIFYING TOTAL AUTHORIZED WEIGHT NOT EXCEEDED
Taxied into truck box ripped gash left underside wing tip		
patch underside fuselage between landing gear ripped by brush landing in Sand Hills		