



Accident at Hanover Passenger train No. 6, running between Owen Sound and Stratford was derailed about one and a half miles north of Hanover some days ago. The train was being hauled by two locomotives owing to heavy snow, and was travelling at the rate of about thirty miles an hour. The accident was caused by a steel plate about two feet by one having been fastened to the rail by some unknown person and was evidently a part of a land plough. The two engines and three first coaches were derailed, the engines being ditched, one of them completely turned round. Ten persons were injured.



Suffragettes before the Capitol The upper photo shows some of the Virginia Cavalry Delegation to Washington on horseback, guarding the line of parade in the shadow of the Capitol looming in the background. The lower photo shows some of the suffragettes garbed as "Women of the Bible Lands" with their float.