

BRAKE CHAIN BROKE

Newspapers of August 16th described a trolley disaster in which the conductor was killed and nine passengers injured. The brake chain broke on a steep grade and the car overturned on a curve.

The Sterling Safety Brake has two chains, running in sprockets. Should the working chain snap, the safety chain, which runs idly and unworn, would be instantly in service. This is the safest device known. It is not costly. Thousands of cars have it. Ask for references.

STERLING-MEAKER COMPANY

NEWARK, N. J., U. S. A.

JAS. W. PYKE & COMPANY

CANADIAN REPRESENTATIVES

FRIED. KRUPP, ESSEN, GERMANY.

Steel Rails.


Wrought Iron Steel-Tyred Disc Wheels

Locomotive and Car Wheel Tyres.

Axles, Crank Pins, Forgings, Etc.

FOR STEAM AND
ELECTRIC RAILWAYS.


OFFICE: MERCHANTS BANK BUILDING **MONTREAL.**
205 ST. JAMES STREET,



New, 25 Pounds

STEEL BACK CAR BRAKE SHOE

Can be applied to any type of shoe. The **Steel Back** doubles the life of the shoe.



Scrap, 5 Pounds


Steel Back Brake Shoe

ONLY SAFE SHOE FOR HIGH SPEED BRAKES

More dense and durable than common Cast Iron


Perfecto Driver Brake Shoe

THE BEST SHOE FOR GENERAL LOCOMOTIVE
SERVICE



Back View

PERFECTO DRIVER BRAKE SHOE



Contact Surface

AMERICAN BRAKE SHOE & FOUNDRY CO.

N. J. HOLDEN, Agent, 18 ST. PETER ST., MONTREAL

MISCELLANEOUS IRON AND
STEEL CASTINGS