

age good; plumbing finished but not connected with sewer.

No. 37 Maynard; Condition of premises bad; no plumbing or drainage in house; sink in yard; cellar wet.

No. 26 Blowers; Drainage good; plumbing fair with the exception of a *hopper w. c. in basement*, which is offensive.

No. 81 Duke St.; Plumbing very defective; no trap to main drain; soil pipe badly connected with crock drain; joints in waste-pipe badly made and leaking.

No. 140 Grafton: An offensive w. c. in yard; soil pipe and sink waste pipe not trapped; the absence of trapping allows sewer gas to enter the house, thus rendering the place offensive and unwholesome.

No. 18 Cunard: Drainage defective; sink waste pipes have no traps; joints in waste-pipe all open; sewer gas escaping into house.

No. 32 Bauer? Plumbing very bad; connection between waste-pipe and crock drain defective; joints in plumbing work badly made; no trap to prevent sewer; gas entering house.

No. 68 Gottingen: Sink waste-pipes void of proper trap; joints leaking.

No. 126 Tower Road? Plumbing defective; sink waste-pipes badly connected and leaking at joints; an old pattern, *unventilated hopper w. c. in basement*.

No. 21 Bauer: Plumbing defective; sink waste-pipes have open joints and are badly connected with crock drain in cellar; sewer gas entering house.

No. 147 Albemarle: W. c. soil pipe stopped up, and filthy matter running over the place; no trap to sink waste-pipe.

No. 71 Creighton: Drainage good; no plumbing in house; hydrant and sink in yard.

No. 30 Park (s): Plumbing and drainage good; entire woodwork, flooring, etc., in cellar decayed, consequently place unwholesome.

No. 43 Seymour: No plumbing or drainage; six inches of water in cellar; water supply pipe bursted.

No. 92 Water (Up.): Joints connecting hopper w. c. with soil pipe defective; soil and waste-pipes not made of proper material; should be replaced by one of cast iron properly jointed and trapped.

No. 241 Albemarle: Waste water pipe leaks in cellar; no drainage; cellar flooded with filthy liquid matter.

No. 67 Sackville: Plumbing and drainage bad; no trap on sink waste-pipe.

No. 204 Grafton: Plumbing fair; has a wooden box drain in cellar which is badly connected.

No. 30 South: Plumbing fair; drainage good; an *unventilated w. c. in basement*.

No. 37 Henry St.; New house; plumbing fair; drainage good; some of the joints in soil pipe badly connected.

No. 95 Morris; Drainage bad; sewer gas escapes in house.

No. 8 Victoria Lane; No trap on sink waste-pipe; wooden box drain in cellar which is badly connected.

No. 7 Letson's Lane; Drainage good; plumbing fair; sink waste-pipe well trapped.

No. 124 Henry; Plumbing bad; no trap on sink waste-pipe; house drained by a crock drain.

No. 36 Creighton; This house has no drain and no plumbing work.

No. 56 Queen; 6 inches crock pipe under kitchen floor wide open; sink waste-pipe poorly connected; a *hopper w. c. in basement which is very offensive*; sewer gas entering house; plumbing work should be thoroughly overhauled and properly ventilated.

No. 99 Queen; Sink waste-pipe connected to a wooden box shut and water conductor's from roof connected with it also; sewer gas entering house.

No. 57 Victoria Road; Sanitary conditions of house very bad; a *hopper w. c. in cellar which is offensive*, and should be removed.

No. 90 Pleasant; Has a *hopper w. c. in basement*; cellar damp.

No. 19 North; Joints in crock pipe