

APPENDIX No. 3.

STATEMENT of Soundings made in the Navigable Channel of the River Ottawa,
between Grenville and Ottawa, May, 1877.

Locality of Soundings.		Depth. Feet.	Quality of Material brought up.
Between Grenville and the Wharf at L'Original		50	Hard, pure clay.
do	do	50	do
do	do	50	do
do	do	50	do
do	do	50	do
do	do	50	do
do	do	50	do
Three and a-half miles from Grenville.....		51	do
Two miles above L'Original		100	Soft clay.
do		95	do
Opposite point above L'Original.....		62	Clay and a little sawdust.
do		62	Pure clay.
Opposite L'Original Lighthouse.....		43	do
Half a mile above do		104	do
do below Major's Wharf.....		160	Bare rock.
Opposite Papineau House.....		66	Pure clay.
At Island above do		82	do
Above Island		70	Clay and small gravel.
do		70	Very hard clay.
do		70	do and large gravel.
do		70	Very hard clay.
Four miles above Montebello.....		57	do
One mile below North Nation River.....		60	Hard clay.
Half a mile do		53	do
Near Island, north side		56	Fine sand, a little sawdust.
Close to River Nation		60	Fine sand, hard bottom.
Opposite do		36	Blue clay, hard and pure.
Above do		36	Red clay.
do do		40	Hard blue clay.
do do		66	do
do do		62	Fine sand.
Two and a half miles below Thurso.....		24	do
Two do do		28	do
Opposite Island do		40	do
Above Island do		48	do
do		48	Coarse sand.
do		48	do
Half a mile below Thurso		43	do
Three miles below Rockland.....		30	do
A little further up do		30	do
do do		40	Fine sand.
do do		48	do
do do		75	do
do do		50	do
Opposite opening to Bay, Rockland.		47	do