

ONE 30 H.P. ENGINE

Low Water Mark
Lowest known Water Mark

AT


X

GRAVEL AND BOULDERS OVERLYING HARDPAN

back to 1 Engine

supported on Runners in Trench, previous to Immersion

1 1/2" diam. steel cable attached to 1 Engine



COUVER WATER-WORKS; CROSS SECTION OF THE FI

Shewing position of Flexible 12 inch Main and stationary

Horizontal and Vertical Scale of feet

