



Photo—Canada Pictures (Toronto)

Yonge St. looking north from Melinda. In the foreground may be seen the completed decking in this area, and proceeding through the photograph, the top lift excavation and temporary suspension of utilities operating in the King intersection will be observed. Track and track-bed are removed between King and Adelaide. In background a pile driver is in operation between Adelaide and Richmond Sts.