



Figure 15. Thermal infrared linescan image of an airport. White is "hot" and black is "cold" in this image. The image was taken at night. Notice the "hot" buried steamlines and trees along the roadsides. Warm auxillary power units (APU's) can be seen near some of the aircraft. One aircraft appears anomalously warm compared to the others. It may have been parked inside the nearby hangar not long before the image was acquired. (Courtesy of Intera Technologies Ltd.)

Box. (Source: Lillesand and Kiefer, op. cit., p. 402.)