




Diagram 1. Showing wrong arrangement of splash board in brine tank cars which prevents free circulation of air.