

possible source of infection for the Montreal water supply is by no means clear as our water is taken from the portion which flows by the north bank of the St. Lawrence. It seems advisable that a careful sanitary inspection of this district should be made




Fig. 7—Diagram showing the condition of Ottawa water above Montreal. (First examination, July 30th, 1891.)




Fig. 8—Diagram showing the condition of Ottawa water above Montreal. (Second examination, Sept. 24th, 1891.)

and a map prepared showing the position of all privies, barns, etc., in order that any possible source of infection should be eliminated. The key to the safety of the Montreal drinking supply may be said to lie between St. Anne and the intake.