Then commences in front of the said Eleventh concession at the West side of the allowance for road between the said sixth and seventh lots marked and observe the line properly. Course N 16° W.

Chs	Remarks
2.00	Good land wood maple beech basswood pine and ironwood
2.50	South, Dry dismal wood beech birch and hemlock
6.00	Good level land wood maple beech basswood pine and ironwood Stiff loam inclining to clay
10.00	to the allowance for road in rear of the said concession The allowance for Road

Then continues my line by commencing in front of the said Twelfth concession at the West side of the allowance for road between the sixth and seventh lots in the said twelfth concession. Course N 16° W.

Chs	Remarks
2.00	Good level land wood maple beech basswood pine ironwood some oak soil clay bottom
3.00	Slow descending to a small stream 2 links wide by ½ link deep soil as before.
3.00	came to a road running E & W which crosses the Island.
12.00	Slow descending to a fine spring brook 3 links wide by 1 link deep Course West
26.40	Slow descending to the allowance for road in rear of the said concession wood and soil the same as the last

The Indians having a great desire to purchase from the owner Charles Sero broken lot number seven in the Thirteenth concession of said Carlwright, which is a frontage between their lands and the Lake, directed me to measure the contents of the said broken frontage, this is as follows namely, commencing in front of the said Thirteenth concession at the South West angle of said lot number 7.

Then North 75° E. 29 Chs 00 Lks description of land and soil before given

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA